

WATER BARRIER - McCARTHY CENTER, MILPITAS, CA.

PRODUCT: WB 36

A common problem for engineers and architects is the issue of water movement from an irrigated planting zone to the substructure of a hardscape area. Unchecked water flows can erode the sub-base, leading to potholes and surface degradation. At the McCarthy Center, a large corporate office park in Silicon Valley, the solution was lining the curbing with 36" depth Water Barrier to prevent underground water migration from damaging the hardscape.



Installation - 1999



Fall 2003